

FIG. 1




FIG. 2






FIG. 4






FIG. 6




FIG. 7

FIG. 5 is a side view of the assembly 500. It shows a vertical member 800 with a horizontal member 802 at the top. A bracket 810 is attached to the side of member 800. A pin 812 is shown passing through member 800. The entire assembly is mounted on a base 520.

FIG. 8C






FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14A




FIG. 14B




FIG. 15




FIG. 16






FIG. 17A




FIG. 17B




FIG. 17C




FIG. 17D




FIG. 18




FIG. 19




FIG. 20





FIG. 21







FIG. 23











FIG. 24B








FIG. 27




FIG. 28




FIG. 29

30/80




FIG. 30




FIG. 31

31/80




FIG. 32




FIG. 33




FIG. 34A




FIG. 34B






FIG. 35A




FIG. 35B

35/80




FIG. 35C




FIG. 36




FIG. 37A




FIG. 37B




FIG. 38A




FIG. 38B






FIG. 39A




FIG. 39B




FIG. 40




FIG. 41





FIG. 42



I-I

FIG. 42A





FIG. 42B



II-II

FIG. 42C




FIG. 42D




FIG. 42E






FIG. 43




FIG. 44




FIG. 45

52/80




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50






FIG. 51




FIG. 52A




FIG. 52B




FIG. 52C




FIG. 53A




FIG. 53B




FIG. 53C








FIG. 55A




FIG. 55B




FIG. 56




FIG. 57




FIG. 58A




FIG. 58B




FIG. 59




FIG. 60




FIG. 61






FIG. 62









FIG. 63










FIG. 69




FIG. 70




FIG. 71




FIG. 72




FIG. 73